



Table of Contents

1. Overview	2. BASIC Scores History
3. BASIC Measures	4. KPI: BASIC Measures by Cargo Group
5. Estimated ISS Score	6. Investigation Results
7. Penalties History	8. Acute Critical Violations
9. Red Flag Violation Details	10. DOT Registration Information
11. DOT MCS-150 History	12. Crash Summary
13. Inspection Summary	14. KPI: Inspection Viol OOS Rates by Cargo Group
15. FHWA Registration Information	16. FHWA Insurance Information
17. FHWA Authorities	18. Severe Violations
19. Violation Report	20. Violation Summary
21. Violation Enforcement Chronology	22. Inspection Violations & OOS Counts
23. Radius Of Operation	24. Inspection & Crash Locations
25. Cargo Hot Spots	26. Inspection Violations & OOS Chronology
27. Percent of Insp & Crash by State	28. VIN Insp Summary by State
29. Violations By Unit Type	30. Equipment Ownership
31. Equipment Details	32. Vehicle Age
33. States of Power Unit Registrations	34. Equipment Acquisitions
35. Driver Details	36. Shared VIN Summary
37. Shipper Table	38. Safety Summary
39. Safety Details	40. Crash Detail Color Coded PDF
41. Inspections with Shared Equipment	42. Inspection Tabular Details
43. Inspection Summary By Month	44. VIN Inspection Violation Details
45. Inspection History	46. Crash Hot Spots
47. DOT MCS-150 History Equipment and Driver Details	48. Chameleon



Business Address

21812 ROSCOE BLVD APT 21
CANOGA PARK, CA
91304

Contact Info

(818)-527-8043

dispatch.trans67@gmail.com

FHWA Address

21812 ROSCOE BLVD APT 21
CANOGA PARK, CA, 91304
Phone: (818)-527-8043

Mailing Address

21812 ROSCOE BLVD APT 21
CANOGA PARK, CA
91304

Overview ToC

Operating Status: AUTHORIZED FOR Property
4 other companies viewed this DOT in the past two months
Crash/PU ratio: 0.0%
Clean Inspection ratio: 33.33%

Estimated BASIC Scores (as of 10/31/2025)

	Unsafe Driving	Hours of Service	Driver Fitness	Controlled Sub. and Alcohol	Vehicle Maintenance	HM Compliance	Crash
Relative Scores	0% ⊖	0% ⊖	0% ○	0% ○	0% ⊖	0% ○	0% ○
Alert Status	No	No	No	No	No	No	No



Estimated Inspection Selection System (ISS) Score: 24
Category: Pass

BASIC Scores History - Unsafe Driving ToC

There are no Scores for this BASIC

BASIC Scores History - Hours of Service ToC

There are no Scores for this BASIC

BASIC Scores History - Driver Fitness ToC

There are no Scores for this BASIC

BASIC Scores History - Controlled Substance ToC

There are no Scores for this BASIC



BASIC Scores History - Vehicle Maintenance ToC

There are no Scores for this BASIC


BASIC Scores History - Crash ToC

There are no Scores for this BASIC

BASIC Scores History - Hazmat ToC

There are no Scores for this BASIC

BASIC Measures: Violation Points per Inspection Trends ToC



* BASIC Measures are the absolute SMS scores that are compared within each Safety Event Group to determine the BASIC Score percentiles. Averages based on fleets with 1-5 power units.



BASIC Measures * - Table ToC

UD-Unsafe Driving, HOS-Hours of Service, DF-Driver Fitness, CS-Controlled Substances, VM-Vehicle Maintenance

Date	UD Measure	UD AC	UD with Viol	HOS Measure	HOS AC	HOS with Viol	DF Measure	DF AC	DF with Viol	CS Measure	CS AC	CS with Viol	VM Measure	VM AC	VM with Viol
10/2025	3.00	N	1	2.25	N	1	0.00	N	0	0.00	N	0	8.50	N	2
09/2025	3.00	N	1	2.25	N	1	0.00	N	0	0.00	N	0	8.50	N	2
08/2025	3.00	N	1	2.25	N	1	0.00	N	0	0.00	N	0	8.50	N	2
07/2025	0.00	N	0	3.60	N	1	0.00	N	0	0.00	N	0	5.20	N	1
06/2025	0.00	N	0	4.50	N	1	0.00	N	0	0.00	N	0	6.50	N	1
05/2025	0.00	N	0	9.00	N	1	0.00	N	0	0.00	N	0	13.00	N	1
04/2025	0.00	N	0	9.00	N	1	0.00	N	0	0.00	N	0	13.00	N	1
03/2025	0.00	N	0	9.00	N	1	0.00	N	0	0.00	N	0	13.00	N	1
02/2025	0.00	N	0	9.00	N	1	0.00	N	0	0.00	N	0	13.00	N	1
01/2025	0.00	N	0	9.00	N	1	0.00	N	0	0.00	N	0	13.00	N	1
12/2024	0.00	N	0	0.00	N	0	0.00	N	0	0.00	N	0	0.00	N	0

* BASIC Measures are the absolute SMS scores that are compared within each Safety Event Group to determine the BASIC Score percentiles.

KPI: BASIC Measures by Fleet Size and Cargo Group ToC

Fleet Size: 1-5 PUs

Cargo Group (Companies)	Unsafe Driving		Hours of Service		Driver Fitness		Controlled Substance		Vehicle Maintenance		HM Compliance		Crash	
	Avg.	Comp. to Avg.	Avg.	Comp. to Avg.	Avg.	Comp. to Avg.	Avg.	Comp. to Avg.	Avg.	Comp. to Avg.	Avg.	Comp. to Avg.	Avg.	Comp. to Avg.
General Freight (490400)	0.79	Worse	0.21	Worse	0.21	Better	0.01	Better	1.88	Worse	0.01	Better	0.06	Better
TRANS67 TRANSPORT INC	3.00		2.25		0.00		0.00		8.50		0.00		0.00	

Estimated ISS Score: 24 Pass ToC About the Inspection Selection System

Estimated ISS Score History - Table ToC

Date	Estimated ISS Score	Recommendation	Algorithm
10/31/2025	24	Pass	Safety Algorithm
09/26/2025	24	Pass	Safety Algorithm
08/29/2025	24	Pass	Safety Algorithm
07/25/2025	72	Optional Inspect	Insufficient Data Algorithm
06/30/2025	72	Optional Inspect	Insufficient Data Algorithm
05/31/2025	69	Optional Inspect	Insufficient Data Algorithm
04/25/2025	65	Optional Inspect	Insufficient Data Algorithm
03/28/2025	65	Optional Inspect	Insufficient Data Algorithm
02/28/2025	64	Optional Inspect	Insufficient Data Algorithm
01/31/2025	68	Optional Inspect	Insufficient Data Algorithm
12/27/2024	63	Optional Inspect	Insufficient Data Algorithm

Investigation Results ToC

No Investigations reported on FMCSA website

Penalties History ToC

There is a problem with the Penalties data on FMCSA website.



Acute Critical Violations (Based on Investigations as per CSA Methodology Appendix A) [ToC](#)

No Data

No red flag violations in the last 24 months

DOT Registration Information: The following information on this specific DOT # is from the Federal DOT (as of Operating Authority)					
DOT Registration: 12/03/2024		Total Power Units: 1		Total Trucks: 1	
Total Trailers: 1		Total Passenger Vehicles: 0			
Status	Entity Type	Organization Type	Nation	Total Cars	Drivers / CDL Drivers
A	C	-	US	0	2* / 2
MCS-150 Date	Op Codes	Shipper Op Codes	Shipper HazMat Op Codes	Latest Review Type	Latest Review Document Number(Date)
10/24/2025	A				()
MCS-150 Mileage (Year)	Record Update Date	Transports Hazmats	DOT Census Date	Recordable Accident Rate	Preventable Accident Rate
1 (2024)	10/24/2025	N		0%	0%
MCS-151 Mileage	Safety Rating (Date)	SEA Accident	SEA Driver	SEA Vehicle	SEA Management
0	None (None)	0%	0%	0%	0%
Classification Codes		Cargo Carried (per MCS-150)			
Authorized-For-Hire		General Freight			

DOT MCS-150 History ToC			(as of 10/28/2025 DOT census)						
Census Date	MCS-150 Date	MCS-150 Mileage	VMT Year	Power Units	Drivers	Trailers	Company Rep1	Company Rep2	Email
10/28/2025	10/24/2025	1	2024	1	2	-	VARINDER SINGH		dispatch.trans67@gmail.com
10/23/2025	10/20/2025	1	2024	1	2	-	VARINDER SINGH		dispatch.trans67@gmail.com
12/9/2024	12/3/2024	0		1	1	-	VARINDER SINGH		

Crash Summary Chart [ToC](#)Crashes Summary - Chart (based on all available crash data)

No Data

Crashes Summary - Table (based on all available crash data) ToC										
	TOTAL	Last 6 months	7-12 months	13-18 months	19-24 months	25-30 months	30-36 months	37-41 months	42-48 months	Over 49 months
Total Reportable	0	0	0	0	0	0	0	0	0	0
Fatalities	0	0	0	0	0	0	0	0	0	0
Injuries	0	0	0	0	0	0	0	0	0	0
Tow Away	0	0	0	0	0	0	0	0	0	0
With Citations	0	0	0	0	0	0	0	0	0	0
Federal Recordable	0	0	0	0	0	0	0	0	0	0
Preventable	0	0	0	0	0	0	0	0	0	0
Crash per Pwr Unit	-	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	-



Inspection Summary **ToC**

The following inspection information is based on results for 24 months prior to: 11/23/2025. Please note that the total inspections number is not necessarily the total of the vehicle, driver and hazmat inspections, as one inspection may have included any combination of the below inspections.

Overall	Vehicle	Driver	Hazmat
(Please note that the total inspections number is not necessarily the total of the vehicle, driver and hazmat inspections, as one inspection may have included any combination of the below inspections) Total Inspections: 3 Total Out of Service: 2 Out of Service: 66.67% National Average: 21.07% Difference: 45.6%	Total Inspections: 3 Total Out of Service: 2 Out of Service: 66.67% National Average: 25.16% Difference: 41.51%	Total Inspections: 3 Total Out of Service: 1 Out of Service: 33.33% National Average: 6.78% Difference: 26.55%	Total Inspections: 0 Total Out of Service: 0 Out of Service: 0.00% National Average: 2.1% Difference: -2.1%

KPI: Inspection Viol OOS Rates by Cargo Group **ToC**

Cargo Group	OVERALL		VEHICLE		DRIVER		HAZMAT	
	Average	Compared to Average	Average	Compared to Average	Average	Compared to Average	Average	Compared to Average
General Freight	29.47%	Worse	25.37%	Worse	13.41%	Worse	0.14%	Better
TRANS67 TRANSPORT INC	66.67%		66.67%		33.33%		0%	

FHWA Registration Information: The following data on this Motor Carrier is from the Federal Hwy Administration (as of 11/20/2025)

Docket Number	DOT Number	Company Name	DBA Name	Address	City	State	Country	ZIP Code
MC1690565	4330151	TRANS67 TRANSPORT INC		21812 ROSCOE BLVD APT 21	CANOGA PARK	CA	US	91304
Phone Number	Fax Number	Mail Address	Mail City	Mail State	Mail Contry	Mail ZIP Code	Mail Phone Number	Mail Fax Number
(818)-527-8043								
Date of Last Change	Freight	Passenger	Household Goods	Active Authority	Pending Authority	Revocation Pending Authority		
11/20/2025	Y	N	N	/ Common /	/	/ Common /		

Insurance Required (as of 11/20/2025) **ToC**

Docket Number	Insurance Type	Insurance Required	Insurance on File
MC1690565	BIPD	\$750k	\$750k
MC1690565	Cargo	No	No
MC1690565	Bond	No	No

Active / Pending Insurance (as of 11/20/2025)

Docket Number	Form	Type	Insurance Carrier	Policy/Surety	Coverage From	Coverage To	Required	On File	Effective Date	Cancel Date
MC1690565	91X	BIPD/Primary	PLATINUM TRANSPORT INSURANCE RRG, INC	PTI003214-00	\$0k	\$750k	\$750k	\$750k	12/16/2024	12/16/2025

Insurance History (as of 11/20/2025)

No Data for Insurance History (as of 11/20/2025)



FHWA Authorities (as of 11/20/2025) ToC								
Docket#	L&I Name	Active Authority	Inactive Authority	Pending Authority	Revocation Pending Authority	Freight	Passenger	Household Goods
MC1690565	TRANS67 TRANSPORT INC	Common /			Common /	Yes	No	No

Authority History (as of 11/20/2025)				
Docket Number	Sub	Auth Type	Original Action	Disposition
MC1690565		COMMON	GRANTED 12/20/2024 12:00:00 AM	

Severe Violations (i.e. those with >= 8 points) - Chart **ToC**

No Data

Severe Violations (i.e. those with >= 8 points) - Table

No Data

Violation Report ToC						
Inspection Date	Inspection State	BASIC	Violation Description	OOS	VIN	Severity Points
07/30/2025	AZ	Vehicle Maintenance	393.70B1CDFWFMIMT20 - COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTENERS ON EITHER SIDE MISSING/INEFFECTIVE.	Yes	3AKJHHDR4LSLN9307	3
07/30/2025	AZ	Vehicle Maintenance	393.11A1LCHL - Lighting - Lamps improper color height location.	No	3AKJHHDR4LSLN9307	6
07/30/2025	AZ	Vehicle Maintenance	393.11A1CSURR - CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RETRO REFLECTIVE SHEETING MISSING ON VEHICLE MANUFACTURED ON OR AFTER JULY 1 1997.	No	3AKJHHDR4LSLN9307	3
07/30/2025	AZ	Unsafe Driving	392.2SLLUP - STATE/LOCAL LAWS - UNLAWFULLY PARKING /LEAVING VEHICLE ON ROADWAY.	No	3AKJHHDR4LSLN9307	1
01/22/2025	AZ	Vehicle Maintenance	393.9ALTSI - LIGHTING - TURN SIGNAL - ANY INOPERATIVE ON THE REARMOST VEHICLE.	Yes	1JJV532B3LL174761	6
01/22/2025	AZ	Hours-Of-Service	395.30B2ELDDFC24 - HOS (ELD) - DRIVER FAILING TO CERTIFY THE RECORD IMMEDIATELY AFTER THE FINAL REQUIRED ENTRY HAS BEEN MADE OR CORRECTED FOR THE 24 HOUR PERIOD.	No	3AKJHHDR4LSLN9307	1
01/22/2025	AZ	Hours-Of-Service	395.8K2HOSP - HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION RODS FOR THE PREVIOUS SEVEN CONSECUTIVE DAYS AND AVAILABLE FOR INSPECTION WHILE ON DUTY	Yes	3AKJHHDR4LSLN9307	5
01/22/2025	AZ	Hours-Of-Service	395.24 - HOS (ELD) - ELD FORM AND MANNER	No	3AKJHHDR4LSLN9307	1
01/22/2025	AZ	Vehicle Maintenance	392.2SLLMF - STATE/LOCAL LAWS - WHEEL (MUD) FLAPS MISSING OR DEFECTIVE.	No	1JJV532B3LL174761	1
01/22/2025	AZ	Vehicle Maintenance	392.8D - DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMENT.	No	3AKJHHDR4LSLN9307	2
01/22/2025	AZ	Vehicle Maintenance	393.95F - No / insufficient warning devices	No	3AKJHHDR4LSLN9307	2

No filters were applied when generating this report, see the live report for more options.




Violation Summary **ToC**

BASIC	Violation Group	Code	Description	# of Violations	# of OOS Violations	Severity Points
Vehicle Maintenance	Lighting	393.11A1LCHL	Lighting - Lamps improper color height location.	1	0	6
Vehicle Maintenance	Lighting	393.9ALTSI	LIGHTING - TURN SIGNAL - ANY INOPERATIVE ON THE REARMOST VEHICLE.	1	1	6
Hours-Of-Service (HOS) Compliance	Incomplete/Wrong Log	395.8K2HOSP	HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION RODS FOR THE PREVIOUS SEVEN CONSECUTIVE DAYS AND AVAILABLE FOR INSPECTION WHILE ON DUTY	1	1	5
Vehicle Maintenance	Coupling Devices	393.70B1ICDFWFMIMT 20	COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTENERS ON EITHER SIDE MISSING/INEFFECTIVE	1	1	3
Vehicle Maintenance	Reflective Sheeting	393.11A1CSURR	CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RETRO REFLECTIVE SHEETING MISSING ON VEHICLE MANUFACTURED ON OR AFTER JULY 1 1997.	1	0	3
Vehicle Maintenance	Emergency Equipment	392.8D	DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMENT.	1	0	2
Vehicle Maintenance	Emergency Equipment	393.95F	No / insufficient warning devices	1	0	2
Unsafe Driving	Other Driver Violations	392.2SLLUP	STATE/LOCAL LAWS - UNLAWFULLY PARKING /LEAVING VEHICLE ON ROADWAY.	1	0	1
Vehicle Maintenance	Windshield/ Glass/ Markings	392.2SLLMF	STATE/LOCAL LAWS - WHEEL (MUD) FLAPS MISSING OR DEFECTIVE.	1	0	1
Hours-Of-Service (HOS) Compliance	Other Log/Form & Manner	395.24	HOS (ELD) - ELD FORM AND MANNER	1	0	1
Hours-Of-Service (HOS) Compliance	Other Log/Form & Manner	395.30B2ELDDFC24	HOS (ELD) - DRIVER FAILING TO CERTIFY THE RECORD IMMEDIATELY AFTER THE FINAL REQUIRED ENTRY HAS BEEN MADE OR CORRECTED FOR THE 24 HOUR PERIOD.	1	0	1

No filters were applied when generating this report, see the live report for more options.




Violation Enforcement Chronology - Chart ToC



Violation Enforcement Chronology - Table ToC

	2021	2022	2023	2024	2025
Traffic Enforcement	0	0	0	0	8
Size/Weight Enforcement	0	0	0	0	0
HazMat Placard Required	0	0	0	0	0
Post Accident	0	0	0	0	0
Controlled Substance/Alcohol	0	0	0	0	0

Inspection Violations & OOS Counts - Chart ToC





Inspection Violations & OOS Counts - Table [ToC](#)


Date Range	Inspections	Violations	Out-of-Services	Crashes
TOTAL	3	11	3	0
1 - 6 months	2	4	1	0
7 - 12 months	1	7	2	0
13 - 18 months	0	0	0	0
19 - 24 months	0	0	0	0
25 - 30 months	0	0	0	0
31 - 36 months	0	0	0	0
37 - 42 months	0	0	0	0
43 - 48 months	0	0	0	0

Radius of Operation (based on Inspections and Crashes during the past 3 years) [ToC](#)

	Total	Drive between 0 and 50 miles radius	Drive between 51 and 200 miles radius	Drive between 201 and 300 miles radius	Drive between 301 and 400 miles radius	Drive between 401 and 500 miles radius	Drive between 501 and 600 miles radius	Drive beyond 600 miles radius
Power Units (i.e. unique VINs)	1	0	0	0	0	1	0	0
Percent	100%	0%	0%	0%	0%	100%	0%	0%



Inspection & Crash Locations - Chart ToC



Inspection & Crash Locations - Table ToC

State	Inspections					Violations					Out-of-Services					Crashes				
	2021	2022	2023	2024	2025	2021	2022	2023	2024	2025	2021	2022	2023	2024	2025	2021	2022	2023	2024	2025
TOTAL	0	0	0	0	3	0	0	0	0	11	0	0	0	0	3	0	0	0	0	0
AZ	0	0	0	0	2	0	0	0	0	11	0	0	0	0	3	0	0	0	0	0
CA	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Hot Spot Summary ToC

Year	Month	Level 5	Level 5 %	Level 4	Level 4 %	Level 3	Level 3 %	Level 2	Level 2 %	Level 1	Level 1 %	Level 0	Level 0 %	Levels 1 - 5	Levels 1 - 5 %
2025	July (Partial)	1	33.33%	0	0.00%	0	0.00%	0	0.00%	0	0.00%	1	33.33%	1	33.33%
2025	January	0	0.00%	0	0.00%	0	0.00%	0	0.00%	0	0.00%	1	33.33%	0	0.00%




Totals	1	33.33%	0	0.00%	0	0.00%	0	0.00%	0	0.00%	2	66.66%	1	33.33%
--------	---	--------	---	-------	---	-------	---	-------	---	-------	---	--------	---	--------

Hot Spot Analysis

State	County	Level	Count	Percentage
CA	Los Angeles	5	1	33.33%

Report generated using the last 12 full months of inspection data

Inspection Violation % OOS Chronology - Chart [ToC](#)




Inspection Violation % OOS Chronology - Table [ToC](#)

	2021	2022	2023	2024	2025
Total Violations	0	0	0	0	11
Total Out Of Services	0	0	0	0	3
%OOS Total Violations	0	0	0	0	27.27
Total Driver Violations	0	0	0	0	5
Total Driver Out Of Services	0	0	0	0	1
%OOS Driver Violations	0	0	0	0	20.0
Total PU Violations	0	0	0	0	9
Total PU Out Of Services	0	0	0	0	2
%OOS PU Violations	0	0	0	0	22.22
Total Trailer Violations	0	0	0	0	2
Total Trailer Out Of Services	0	0	0	0	1
%OOS Trailer Violations	0	0	0	0	50.0
Total Hazmat Violations	0	0	0	0	0
Total Hazmat Out Of Services	0	0	0	0	0
%OOS HazMat Violations	0	0	0	0	0



Percent of Insp & Crash by State - Chart ToC



Percent of Insp & Crash by State - Table (based on Inspection data from the last 4 years) ToC

State	Inspections		Violations		Out-of-Services		Crashes	
	Total	Percent	Total	Percent	Total	Percent	Total	Percent
	3	100	11	100	3	100	0	100
AZ	2	66.7	11	100	3	100	0	0
CA	1	33.3	0	0	0	0	0	0

VIN Insp Summary by State (based on inspection from the last 2 years) ToC

VIN	Insp	Viol Pts	Counts in each State			
			AZ		CA	
			Insp	Viol Pts	Insp	Viol Pts
TOTALS	8/48*	3/31**	2	31	1	0
3AKJHHDR4LSLN9307	3	23	2	23	1	0
1GR1A0624NB333300	1	1	1	1	0	0
1JJV532B3LL174761	1	7	1	7	0	0
1UYVS253XK3760325	1	0	0	0	1	0

*<Total number of inspections for these 4 VIN(s)>/<Total number of inspections for these 2 state(s)>

**<Total severity sum for these 4 VIN(s)>/<Total severity sum for these 2 state(s)>

Violations By Unit Type ToC

of Violations: 10 Total Severity: 30 based on inspections in the last 2 years

Violation Unit: Driver	# of Violations: 4	Total Severity: 9	% of Total: 30%
Viol. Group: Incomplete/Wrong Log	# of Violations: 1	Total Severity: 5	% of Total: 16.67%
Violation	Number of Occurrences	Viol. Severity	Total Severity
395.8K2HOSP:HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION ROD	1	5	5
Viol. Group: Emergency Equipment	# of Violations: 1	Total Severity: 2	% of Total: 6.67%
392.8D:DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMEN	1	2	2
Viol. Group: Other Log/Form & Manner	# of Violations: 2	Total Severity: 2	% of Total: 6.67%
395.24:HOS (ELD) - ELD FORM AND MANNER	1	1	1
395.30B2ELDDFC24:HOS (ELD) - DRIVER FAILING TO CERTIFY THE RECORD I	1	1	1



Violation Unit: Power Unit	# of Violations: 4	Total Severity: 14	% of Total: 46.67%
Viol. Group: Lighting	# of Violations: 1	Total Severity: 6	% of Total: 20%
Violation	Number of Occurrences	Viol. Severity	Total Severity
393.11A1LCHL:Lighting - Lamps improper color height location.	1	6	6
Viol. Group: Reflective Sheeting	# of Violations: 1	Total Severity: 3	% of Total: 10%
393.11A1CSURR:CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RET	1	3	3
Viol. Group: Coupling Devices	# of Violations: 1	Total Severity: 3	% of Total: 10%
393.70B1CDFWMIMT20:COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTEN	1	3	3
Viol. Group: Emergency Equipment	# of Violations: 1	Total Severity: 2	% of Total: 6.67%
393.95F:No / insufficient warning devices	1	2	2
Violation Unit: Trailer	# of Violations: 2	Total Severity: 7	% of Total: 23.33%
Viol. Group: Lighting	# of Violations: 1	Total Severity: 6	% of Total: 20%
Violation	Number of Occurrences	Viol. Severity	Total Severity
393.9ALTSI:LIGHTING - TURN SIGNAL - ANY INOPERATIVE ON THE RE	1	6	6
Viol. Group: Windshield/ Glass/ Markings	# of Violations: 1	Total Severity: 1	% of Total: 3.33%
392.2SLLMF:STATE/LOCAL LAWS - WHEEL (MUD) FLAPS MISSING OR DE	1	1	1

Equipment Ownership **ToC**Equipment Ownership (based on MCS-150 dated 10/24/2025)

	Trucks	Tractors	Trailers	Motor Coaches	Vans
Owned	0	1	1	0	0
Term Leased	0	0	0	0	0
Trip Leased	0	0	0	0	0
Total No.	0	1	1	0	0

Equipment Details Power Units **ToC**

VIN	Latest Insp Date	Year	Make	Model	Body Class	Body Type	Axles	Len	Fuel Type
3AKJHHDR4LS LN9307	07/30/2025	2020	FREIGHTLINER	Cascadia	Truck-Tractor	-	-	-	-

Equipment Details Trailers

VIN	Latest Insp Date	Year	Make	Model	Body Class	Body Type	Axles	Len	Fuel Type
1GR1A0624NB3 33300	07/30/2025	2022	GREAT DANE TRAILERS	Great Dane Trailers	Trailer	-	2	53	Not Applicable
1UYVS253XK37 60325	07/02/2025	2019	UTILITY TRAILER MANUFACTUR ER	Utility Trailer Manufacturer	Trailer	Van Trailer	2	53	-
1JJV532B3LL17 4761	01/22/2025	2020	WABASH	Refrigerated Van	Trailer	Van Trailer	2	53	-

Vehicle Age **ToC**

Year	# Power Units	PU Percentage	# Trailers	Trailres Percentage
2022	0	0.00%	1	33.33%
2020	1	100.00%	1	33.33%
2019	0	0.00%	1	33.33%

Based on 24 months of inspection data, see the live report for more options

States of Power Unit Registrations **ToC**

State	AZ	CA
Number of Power Units	1	1



Equipment Acquisitions - Table ToC							
	Power Units inspected for 1st time in past 12 months	Power Units inspected for 1st time in past 24 months	Power Units inspected during entire date range		Trailers inspected for 1st time in past 12 months	Trailers inspected for 1st time in past 24 months	Trailers inspected during entire date range
Unique VINs	1	1	1		3	3	3
Unique License Plates	1	1	1		3	3	3
License Plate States	1	1	1		3	3	3

Driver Details ToC Driver Details (based on MCS-150 dated 10/24/2025)			
	Within 100 mi	Beyond 100 mi	TOTAL
# Drivers Interstate	0	2	2
# Drivers Intrastate	0	0	0
TOTAL	0	2	/
Avg. # Trip Lease Drivers/Mo: 0 # Drivers Grand Total: 2 # Drivers Commercially Licensed: 2			



Shared VIN Summary ToC
No Data


SHIPPERS DETAIL ToC based on Inspection results for the last 4 years

Shipper Name	Number of Inspections	Shipper Name	Number of Inspections
AMAZON	1	POLY AMERICA L P	1
VANTIX	1		



Carrier Underwriting Report Safety Summary ToC





See the Excel file for the complete analysis



Violations is in (1-6/7-12/13-24mo)


Shaded = Out Of Service Violation												
Violation Group			Lighting	Lighting	Coupling Devices	Incomplete/Wrong Log	Reflective Sheeting	Emergency Equipment	Emergency Equipment	Other Driver Violations	Windshield/Glass/Markings	Other Log/Form & Manner
Violation Description	Total Time-weighted Points by VIN	% of Total Time-weighted Points by VIN	Lighting - Lamps improper color height location.	LIGHTING - TURN SIGNAL - ANY INOPERATIVE ON THE REARMOST VEHICLE.	COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTENERS ON EITHER SIDE MISSING/INEFFECTIVE.	HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION RODS FOR THE PREVIOUS SEVEN CONSECUTIVE DAYS AND AVAILABLE FOR INSPECTION WHILE ON DUTY	CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RETRO REFLECTIVE SHEETING MISSING ON VEHICLE MANUFACTURED ON OR AFTER JULY 1 1997.	DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMENT.	No / insufficient warning devices	STATE/LOCAL LAWS - UNLAWFULLY PARKING /LEAVING VEHICLE ON ROADWAY.	STATE/LOCAL LAWS - WHEEL (MUD) FLAPS MISSING OR DEFECTIVE.	HOS (ELD) - ELD FORM AND MANNER
Driver Resp			No	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes
Total Time-weighted Points			18	16	15	14	9	4	4	3	2	2
% Total Time-Wt Pts			20.22	17.98	16.85	15.73	10.11	4.49	4.49	3.37	2.25	2.25
3AKJHHDR4LSLN9307	68	76.40	18 (1/0/0)		15 (1/0/0)	14 (0/1/0)	9 (1/0/0)	4 (0/1/0)	4 (0/1/0)			2 (0/1/0)
1JJV532B3LL174761	18	20.22		16 (0/1/0)							2 (0/1/0)	
1GR1A0624NB333300	3	3.37								3 (1/0/0)		



SAFETY ANALYSIS ToC

Unsafe Driving






See the Excel file for the complete analysis # Violations is in (1-6/7-12/13-24mo)

Shaded = Out Of Service Violation			
Violation Group			Other Driver Violations
Violation Description	Total Time-weighted Points by VIN	% of Total Time-weighted Points by VIN	STATE/LOCAL LAWS - UNLAWFULLY PARKING /LEAVING VEHICLE ON ROADWAY.
Driver Resp			Yes
Total Time-weighted Points			3
% Total Time-Wt Pts			100
1GR1A0624NB333300	3	100	3 (1/0/0)


HOS Compliance



Carrier Software
 1-800-646-5152
 info@CarrierSoftware.com

CONFIDENTIAL - Intended for use by Amerigo Insurance Agency - Date: 11/24/2025


TRANS67 TRANSPORT INC - DOT# 4330151 / MC1690565



See the Excel file for the complete analysis

Violations is in (1-6/7-12/13-24mo)

Shaded = Out Of Service Violation



Carrier Software
 1-800-646-5152
 info@CarrierSoftware.com


CONFIDENTIAL - Intended for use by Amerigo Insurance Agency - Date: 11/24/2025

TRANS67 TRANSPORT INC - DOT# 4330151 / MC1690565

Violation Group			Incomplete/Wrong Log	Other Log/Form & Manner	Other Log/Form & Manner
Violation Description	Total Time-weighted Points by VIN	% of Total Time-weighted Points by VIN	HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION RODS FOR THE PREVIOUS SEVEN CONSECUTIVE DAYS AND AVAILABLE FOR INSPECTION WHILE ON DUTY	HOS (ELD) - ELD FORM AND MANNER	HOS (ELD) - DRIVER FAILING TO CERTIFY THE RECORD IMMEDIATELY AFTER THE FINAL REQUIRED ENTRY HAS BEEN MADE OR CORRECTED FOR THE 24 HOUR PERIOD.
Driver Resp			Yes	Yes	Yes
Total Time-weighted Points			14	2	2
% Total Time-Wt Pts			77.78	11.11	11.11
3AKJHHDR4LSLN9307	18	100	14 (0/1/0)	2 (0/1/0)	2 (0/1/0)



Driver Fitness





Time-Weighted Violation Points - no data available to draw a chart
Time-Weighted Severity Points by Vehicle - no data available to draw a chart


See the Excel file for the complete analysis # Violations is in (1-6/7-12/13-24mo)

Shaded = Out Of Service Violation		
Violation Group		
Violation Description	Total Time-weighted Points by VIN	% of Total Time-weighted Points by VIN
Driver Resp		
Total Time-weighted Points		
% Total Time-Wt Pts		



Vehicle Maintenance





Carrier Software
 1-800-646-5152
 info@CarrierSoftware.com

CONFIDENTIAL - Intended for use by Amerigo Insurance Agency - Date: 11/24/2025

TRANS67 TRANSPORT INC - DOT# 4330151 / MC1690565

See the Excel file for the complete analysis

Violations is in (1-6/7-12/13-24mo)

Shaded = Out Of Service Violation									
Violation Group			Lighting	Lighting	Coupling Devices	Reflective Sheeting	Emergency Equipment	Emergency Equipment	Windshield/ Glass/ Markings
Violation Description	Total Time-weighted Points by VIN	% of Total Time-weighted Points by VIN	Lighting - Lamps improper color height location.	LIGHTING - TURN SIGNAL - ANY INOPERATIVE ON THE REARMOST VEHICLE.	COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTENERS ON EITHER SIDE MISSING/INEFFECTIVE.	CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RETRO REFLECTIVE SHEETING MISSING ON VEHICLE MANUFACTURED ON OR AFTER JULY 1 1997.	No / insufficient warning devices	DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMENT.	STATE/LOCAL LAWS - WHEEL (MUD) FLAPS MISSING OR DEFECTIVE.
Driver Resp			No	Yes	Yes	Yes	Yes	Yes	Yes
Total Time-weighted Points			18	16	15	9	4	4	2
% Total Time-Wt Pts			26.47	23.53	22.06	13.24	5.88	5.88	2.94
3AKJHHDR4LSLN9307	50	73.53	18 (1/0/0)		15 (1/0/0)	9 (1/0/0)	4 (0/1/0)	4 (0/1/0)	
1JJV532B3LL174761	18	26.47		16 (0/1/0)					2 (0/1/0)

COLOR CODED CRASH TABLE ToC

No crashes have been reported by the DOT on this Motor Carrier

INSPECTIONS WITH SHARED EQUIPMENT:

No Data



LEGEND

Vehicle Information

Inspection for DOT # being analyzed

Inspection for Different DOT

Crash Information for specific VIN

INSPECTION DETAILS for ALL Inspections

PDF shows the first 100 Power Unit & Trailer VINs with most recent inspections using data from the last 4 years

POWER UNIT Inspections Section

VIN: 3AKJHHDR4LSLN9307				Unit: Truck Tractor		Year: 2020	Make: FREIGHTLINER	
DOT No: 4330151		Docket No: MC1690565		Name: TRANS67 TRANSPORT INC			Interstate: Yes	
Date	Unit License	Unit Lic State	Violation Unit	Violation Description		Severity	OOS	Citation
07/30/2025	ZP53771	CA	1	393.70B1ICDFWFMIMT20 - COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTENERS ON EITHER SIDE MISSING/INEFFECTIVE.		3	Yes	
07/30/2025	ZP53771	CA	C	392.2SLLUP - STATE/LOCAL LAWS - UNLAWFULLY PARKING /LEAVING VEHICLE ON ROADWAY.		1	No	
07/30/2025	ZP53771	CA	1	393.11A1CSURR - CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RETRO REFLECTIVE SHEETING MISSING ON VEHICLE MANUFACTURED ON OR AFTER JULY 1 1997.		3	No	
07/30/2025	ZP53771	CA	1	393.11A1LCHL - Lighting - Lamps improper color height location.		6	No	
07/02/2025	ZP53771	CA	-			-	-	-
01/22/2025	ZP53771	CA	D	395.30B2ELDDFC24 - HOS (ELD) - DRIVER FAILING TO CERTIFY THE RECORD IMMEDIATELY AFTER THE FINAL REQUIRED ENTRY HAS BEEN MADE OR CORRECTED FOR THE 24 HOUR PERIOD.		1	No	
01/22/2025	ZP53771	CA	D	392.8D - DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMENT.		2	No	
01/22/2025	ZP53771	CA	D	395.8K2HOSP - HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION RODS FOR THE PREVIOUS SEVEN CONSECUTIVE DAYS AND AVAILABLE FOR INSPECTION WHILE ON DUTY		5	Yes	
01/22/2025	ZP53771	CA	1	393.95F - No / insufficient warning devices		2	No	
01/22/2025	ZP53771	CA	D	395.24 - HOS (ELD) - ELD FORM AND MANNER		1	No	
DOT No: 96606		Docket No: MC119837		Name: OZARK MOTOR LINES INC			Interstate: Yes	
Date	Unit License	Unit Lic State	Violation Unit	Violation Description		Severity	OOS	Citation
01/02/2023	K5152HY	TN	1	393.9 - Inoperative required lamps		2	No	
02/28/2022	K5152HY	TN	-			-	-	-
DOT No: 1426957		Docket No: MX539582		Name: AGUILAS DEL DESIERTO DE BAJA CALIFORNIA S DE RL DE CV			Interstate: Yes	
Date	Unit License	Unit Lic State	Violation Unit	Violation Description		Severity	OOS	Citation
05/08/2019		UK	-			-	-	-

TRAILER Inspections Section

VIN: 3AKJHHDR4LSLN9307				Unit: Truck Tractor		Year: 2020	Make: FREIGHTLINER	
DOT No: 4330151		Docket No: MC1690565		Name: TRANS67 TRANSPORT INC			Interstate: Yes	



Date	Unit License	Unit Lic State	Violation Unit	Violation Description	Severity	OOS	Citation
07/30/2025	ZP53771	CA	1	393.70B1ICDFWFMIMT20 - COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTENERS ON EITHER SIDE MISSING/INEFFECTIVE.	3	Yes	
07/30/2025	ZP53771	CA	C	392.2SLLUP - STATE/LOCAL LAWS - UNLAWFULLY PARKING /LEAVING VEHICLE ON ROADWAY.	1	No	
07/30/2025	ZP53771	CA	1	393.11A1CSURR - CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RETRO REFLECTIVE SHEETING MISSING ON VEHICLE MANUFACTURED ON OR AFTER JULY 1 1997.	3	No	
07/30/2025	ZP53771	CA	1	393.11A1LCHL - Lighting - Lamps improper color height location.	6	No	
07/02/2025	ZP53771	CA	-	-	-	-	-
01/22/2025	ZP53771	CA	D	395.30B2ELDDFC24 - HOS (ELD) - DRIVER FAILING TO CERTIFY THE RECORD IMMEDIATELY AFTER THE FINAL REQUIRED ENTRY HAS BEEN MADE OR CORRECTED FOR THE 24 HOUR PERIOD.	1	No	
01/22/2025	ZP53771	CA	D	392.8D - DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMENT.	2	No	
01/22/2025	ZP53771	CA	D	395.8K2HOSP - HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION RODS FOR THE PREVIOUS SEVEN CONSECUTIVE DAYS AND AVAILABLE FOR INSPECTION WHILE ON DUTY	5	Yes	
01/22/2025	ZP53771	CA	1	393.95F - No / insufficient warning devices	2	No	
01/22/2025	ZP53771	CA	D	395.24 - HOS (ELD) - ELD FORM AND MANNER	1	No	
DOT No: 96606		Docket No: MC119837		Name: OZARK MOTOR LINES INC		Interstate: Yes	
Date	Unit License	Unit Lic State	Violation Unit	Violation Description	Severity	OOS	Citation
01/02/2023	K5152HY	TN	1	393.9 - Inoperative required lamps	2	No	
02/28/2022	K5152HY	TN	-	-	-	-	-
DOT No: 1426957		Docket No: MX539582		Name: AGUILAS DEL DESIERTO DE BAJA CALIFORNIA S DE RL DE CV		Interstate: Yes	
Date	Unit License	Unit Lic State	Violation Unit	Violation Description	Severity	OOS	Citation
05/08/2019		UK	-	-	-	-	-

Inspection Summary By Month (based on inspections from the last 4 years) [ToC](#)

Year-Month	Number of Inspections	Number of Power Units	Total Violations	Total OOS Inspections	Total Severity Points	Number of Crashes
2025-07	2	2	4	1	13	0
2025-01	1	1	7	1	18	0

Note: The most recent month's counts may not include all the inspections for that month.

VIN Inspection Violation Details [ToC](#)

of VINs: 3 # of Insp: 4 Severity Weight: 61 Avg. Weight/VIN: 15.3 (based on inspections in the last 4 years, showing top 50 VINs inspected most recently)

VIN 1GR1A0624NB333300		# of Inspections: 1		Total Severity: 12		Percentage of Total: 19.67%		Avg. Weight Per Inspection: 12.0	
Inspection Date	Inspection ID	Inspection State	Location Description	Total Severity	# of Violations	Shipper Name	Inspection Level	Post Accident	Out of Service
07/30/2025	85377073	AZ	CASA GRANDE AZ	12	3	AMAZON	2	No	Yes
BASIC		Unit Type		Severity		Description		Out of Service	
Vehicle Maintenance		Semi Trailer		6		393.11A1LCHL:Lighting - Lamps improper color height location.		No	
Vehicle Maintenance		Semi Trailer		3		393.11A1CSURR:CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RET		No	
Vehicle Maintenance		Semi Trailer		3		393.70B1ICDFWFMIMT20:COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTEN		Yes	
VIN 3AKJHHDR4LSLN9307		# of Inspections: 2		Total Severity: 31		Percentage of Total: 50.82%		Avg. Weight Per Inspection: 15.5	
Inspection Date	Inspection ID	Inspection State	Location Description	Total Severity	# of Violations	Shipper Name	Inspection Level	Post Accident	Out of Service
07/30/2025	85377073	AZ	CASA GRANDE AZ	13	4	AMAZON	2	No	Yes
BASIC		Unit Type		Severity		Description		Out of Service	
Vehicle Maintenance		Truck Tractor		6		393.11A1LCHL:Lighting - Lamps improper color height location.		No	



Vehicle Maintenance		Truck Tractor		3		393.11A1CSURR:CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RET		No	
Vehicle Maintenance		Truck Tractor		3		393.70B1ICDFWFMIMT20:COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTEN		Yes	
Unsafe Driving		Truck Tractor		1		392.2SLLUP:STATE/LOCAL LAWS - UNLAWFULLY PARKING /LEAVING VEH		No	
Inspection Date	Inspection ID	Inspection State	Location Description	Total Severity	# of Violations	Shipper Name	Inspection Level	Post Accident	Out of Service
01/22/2025	83699368	AZ	KINGMAN AZ	18	7	VANTIX	2	No	Yes
BASIC		Unit Type		Severity		Description		Out of Service	
Vehicle Maintenance		Truck Tractor		6		393.9ALTSI:LIGHTING - TURN SIGNAL - ANY INOPERATIVE ON THE RE		Yes	
Hours-Of-Servce Compliance		Truck Tractor		5		395.8K2HOSP:HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION ROD		Yes	
Vehicle Maintenance		Truck Tractor		2		392.8D:DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMEN		No	
Vehicle Maintenance		Truck Tractor		2		393.95F:No / insufficient warning devices		No	
Vehicle Maintenance		Truck Tractor		1		392.2SLLMF:STATE/LOCAL LAWS - WHEEL (MUD) FLAPS MISSING OR DE		No	
Hours-Of-Servce Compliance		Truck Tractor		1		395.24:HOS (ELD) - ELD FORM AND MANNER		No	
Hours-Of-Servce Compliance		Truck Tractor		1		395.30B2ELDDFC24:HOS (ELD) - DRIVER FAILING TO CERTIFY THE RECORD I		No	
VIN 1JJV532B3LL174761		# of Inspections: 1		Total Severity: 18		Percentage of Total: 29.51%		Avg. Weight Per Inspection: 18.0	
Inspection Date	Inspection ID	Inspection State	Location Description	Total Severity	# of Violations	Shipper Name	Inspection Level	Post Accident	Out of Service
01/22/2025	83699368	AZ	KINGMAN AZ	18	7	VANTIX	2	No	Yes
BASIC		Unit Type		Severity		Description		Out of Service	
Vehicle Maintenance		Semi Trailer		6		393.9ALTSI:LIGHTING - TURN SIGNAL - ANY INOPERATIVE ON THE RE		Yes	
Hours-Of-Servce Compliance		Semi Trailer		5		395.8K2HOSP:HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION ROD		Yes	
Vehicle Maintenance		Semi Trailer		2		392.8D:DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMEN		No	
Vehicle Maintenance		Semi Trailer		2		393.95F:No / insufficient warning devices		No	
Vehicle Maintenance		Semi Trailer		1		392.2SLLMF:STATE/LOCAL LAWS - WHEEL (MUD) FLAPS MISSING OR DE		No	
Hours-Of-Servce Compliance		Semi Trailer		1		395.24:HOS (ELD) - ELD FORM AND MANNER		No	
Hours-Of-Servce Compliance		Semi Trailer		1		395.30B2ELDDFC24:HOS (ELD) - DRIVER FAILING TO CERTIFY THE RECORD I		No	



Inspection History ToC						
Inspection Date	Report Number	Report State	PU VIN	TR VIN	Severity Weight	Time Weight
07/30/2025	1012701918	AZ	3AKJHHDR4LSLN9307 - Truck Tractor	1GR1A0624NB333300 - Semi Trailer		3
Power Unit Violation - OOS Vehicle Maintenance Violation: 393.70B1ICDFWFMIMT20 - COUPLING - MORE THAN 20% OF THE FIFTH WHEEL FASTENERS ON EITHER SIDE MISSING/INEFFECTIVE.					3	
Power Unit Violation - Vehicle Maintenance Violation: 393.11A1LCHL - Lighting - Lamps improper color height location.					6	
Power Unit Violation - Vehicle Maintenance Violation: 393.11A1CSURR - CONSPICUITY SYSTEMS - TRUCK TRACTOR UPPER REAR RETRO REFLECTIVE SHEETING MISSING ON VEHICLE MANUFACTURED ON OR AFTER JULY 1 1997.					3	
Power Unit Violation - Unsafe Driving Violation: 392.2SLLUP - STATE/LOCAL LAWS - UNLAWFULLY PARKING /LEAVING VEHICLE ON ROADWAY.					1	
07/02/2025	NECL003355	CA	3AKJHHDR4LSLN9307 - Truck Tractor	1UYVS253XK3760325 - Semi Trailer		3
01/22/2025	XG09490132	AZ	3AKJHHDR4LSLN9307 - Truck Tractor	1JJV532B3LL174761 - Semi Trailer		2
Trailer Violation - OOS Vehicle Maintenance Violation: 393.9ALTSI - LIGHTING - TURN SIGNAL - ANY INOPERATIVE ON THE REARMOST VEHICLE.					6	
Power Unit Violation - Hours-Of-Service (HOS) Compliance Violation: 395.30B2ELDDFC24 - HOS (ELD) - DRIVER FAILING TO CERTIFY THE RECORD IMMEDIATELY AFTER THE FINAL REQUIRED ENTRY HAS BEEN MADE OR CORRECTED FOR THE 24 HOUR PERIOD.					1	
Power Unit Violation - OOS Hours-Of-Service (HOS) Compliance Violation: 395.8K2HOSP - HOS (PROPERTY) - FAILING TO HAVE IN POSSESSION RODS FOR THE PREVIOUS SEVEN CONSECUTIVE DAYS AND AVAILABLE FOR INSPECTION WHILE ON DUTY					5	
Power Unit Violation - Hours-Of-Service (HOS) Compliance Violation: 395.24 - HOS (ELD) - ELD FORM AND MANNER					1	
Trailer Violation - Vehicle Maintenance Violation: 392.2SLLMF - STATE/LOCAL LAWS - WHEEL (MUD) FLAPS MISSING OR DEFECTIVE.					1	
Power Unit Violation - Vehicle Maintenance Violation: 392.8D - DRIVER - FAILED TO INSPECT /USE EMERGENCY EQUIPMENT.					2	
Power Unit Violation - Vehicle Maintenance Violation: 393.95F - No / insufficient warning devices					2	
Only the first 20 inspections are shown. See the live report for more data.						

Crash Hot Spots ToC					
State	Level 1 (lowest crash frequency)	Level 2	Level 3	Level 4	Level 5 (highest crash frequency)
Arizona	0	1	0	1	0
California	1	0	0	0	0
Total	1	1	0	1	0
Company Level: 2					

Equipment and Driver Details ToC						
MCS-150 Date	Equipment (Owned/Leased/Trip)			Driver Details		
	Tractors	Straight Trucks	Trailers	CDL's	Interstate	Intrastate
10/24/2025	1/0/0	0/0/0	1/0/0	2	2	0
10/20/2025	1/0/0	0/0/0	1/0/0	2	2	0
12/03/2024	1/0/0	0/0/0	1/0/0	0	0	0

Chameleon ToC
Something went wrong while generating Chameleon